03500.012108.2

PATENT V



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

49 //		
in re Patent of:)	
	: Examiner: Jose L. Couso	
AKIHIKO YUSHIYA ET AL.)	
	: Art Unit: 2621	
Appln. No.: 10/626,691)	
	÷ ;	
Filed: July 25, 2003)	
For: IMAGE READING SYSTEM	:	
) :	
U.S. Patent No.: 7,050,657 B2	·)	
	:	
Issued: May 23, 2006) September 29, 2006	
	Certifica OCT 0 6 20	
Commissioner for Patents	o, unce	lte
P.O. Box 1450	UCT 0 6 20)0-
1, O, DOA 1700	• 71	11 IL

CERTIFICATE OF CORRECTION UNDER RULE 323

Sir:

Alexandria, VA 22313-1450

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors of a clerical, typographical, or minor character, that were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

10/04/2006 NBERHE 00000047 7050657 01 FC:1011 100.00 OP

of Correction

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

John A Krause

Attorney for Patentees Registration No. 24,613

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

594735v1

NOT I I WOOD

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

7,050,657 B2

DATED

May 23, 2006

INVENTOR(S) :

AKIHIKO YUSHIYA ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 57, "After" should read -- At--.

COLUMN 2

Line 7, "operation" should read ----operations; and Line 55, "W signal" should read --W signals--.

COLUMN 4

Line 25, "lift" should read --life--.

COLUMN 6

Line 26, "an across sectional" should read --a cross sectional--.

COLUMN 7

Line 33, "repeat" should read --repeats--.

COLUMN 8

Line 10, "output" should read --outputting--.

COLUMN 13

Line 12, "or" should read --of--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. US 7,050,657 B2

No. of add'l. copies @ 30¢ per page

3 **4 1**



Stable Here Ould I'M LINE 'S TRIM LINE 'S TR

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

7,050,657 B2

DATED

May 23, 2006

INVENTOR(S) :

AKIHIKO YUSHIYA ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 15

Line 52, "resisters 310," should read --resistors 310,--.

COLUMN 19

Line 50, "of case" should read --case--;

Line 51, "case" should read --in a case--; and

Line 52, "different" should read --is different--.

MAILING ADDRESS OF SENDER:

PATENT NO. US 7,050,657 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

1 1 2000

Form PTO 1050 (Rev. 3-82)

594735v1

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

7,050,657 B2

DATED

May 23, 2006

INVENTOR(S) :

AKIHIKO YUSHIYA ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 57, "After" should read -- At--.

COLUMN 2

Line 7, "operation" should read ----operations; and Line 55, "W signal" should read --W signals--.

COLUMN 4

Line 25, "lift" should read --life--.

COLUMN 6

Line 26, "an across sectional" should read --a cross sectional--.

COLUMN 7

Line 33, "repeat" should read --repeats--.

COLUMN 8

Line 10, "output" should read --outputting--.

COLUMN 13

Line 12, "or" should read --of--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

594735v1

PATENT NO. US 7,050,657 B2

No. of add'l. copies @ 30¢ per page

~7 1 1 2005



UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

7,050,657 B2

DATED

May 23, 2006

INVENTOR(S) :

AKIHIKO YUSHIYA ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 15

Line 52, "resisters 310," should read --resistors 310,--.

COLUMN 19

Line 50, "of case" should read --case--;

Line 51, "case" should read --in a case--; and

Line 52, "different" should read --is different--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

594735v1

1 1 2006

PATENT NO. <u>US 7,050,657 B2</u>

'OET 1 1 2006

No. of add'l. copies @ 30¢ per page

